





DIP-SWITCH

Example:
800 Steps




SW1-SW3: Steps/Rev
S5 Flank
S6: Direction

DIP-SWITCH



RJ45-PIN-Nr.	Color	Motorsignal
1	white-orange	ENA+
2	orange	ENA-
3	white-green	PUL-
4	blue	DIR+
5	white-blue	DIR-
6	green	PUL-
7	white-brown	Bridged
8	brown	



Ideal power voltage ist 36V DC. Maximum allowed is up to 50V but not recommended as it will shorten the devices lifespan. Use 36V whenever possible!

1. Turn down voltage of power source to 45V with the (adj) potentiometer!
2. Set desired Steps with switch S1-S4
3. Set S5 to OFF (Rising signal flank)
4. Adjust motor direction with S6



Steps	S1	S2	S3	S4
SOFTWARE	ON	ON	ON	ON
800	OFF	ON	ON	ON
1600	ON	OFF	ON	ON
3200	OFF	OFF	ON	ON

Steps lower than 800 can be programmed with the serial connection and a pc using the JMC Software available from our website

Use an adapter or a straight ethernet Patchcable (CAT5-CAT7) to connect the motor to the CNC control! Below you find the pinout of the ethernet patchcable standard.

RJ45-PIN-Nr.	Color	Motorsignal
1	white-orange	ENA+
2	orange	ENA-
3	white-green	PUL-
4	blue	DIR+
5	white-blue	DIR-
6	green	PUL-
7	white-brown	Bridge!
8	brown	

RJ45 Pinout T-568B



- | | |
|-----------------|----------------|
| 1. White Orange | 5. White Blue |
| 2. Orange | 6. Green |
| 3. White Green | 7. White Brown |
| 4. Blue | 8. Brown |